

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Township	DATE 11/30/2016

Arrival Time <u>12:30</u>	Weather: <input type="checkbox"/> Clear <input type="checkbox"/> Overcast <input checked="" type="checkbox"/> Rain <input type="checkbox"/> Hot <input checked="" type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>1:30</u>	Site Condition: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>1.0 hrs</u>	Temp Range: <u>58°F</u> to <u>50°F</u>

CONTRACTOR Torcon	SUBCONTRACTOR(S) JJD, Molly, Reilly
--------------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent _____ Foreman <u>1</u> Operators <u>1</u> Laborers _____ Drivers _____	1) Onsite to observe site conditions and E&S controls due to rain. 2) Sweeper Truck is onsite cleaning roadways and area of worksite just north of Pike Garage (Ithan Avenue and Lancaster Avenue) of tire tracks and minor sediment/debris. Some tire tracks were observed; however, the sweeper truck was continuously traveling the area to address the issue. 3) JJD reset the frame and cover of the storm manhole located south of I-308 as requested. 4) The additional E&S controls installed yesterday at the driveway entrance of Main Lot from Ithan Avenue appear to be functioning to limit silt laden water from entering the storm sewer.
EQUIPMENT USED: Excavator _____ FEL _____ Dump Truck _____ Backhoe <u>1</u> Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
INSPECTOR: Matthew Prusko - Gannett Fleming	