

INSPECTOR'S DAILY REPORT

PROJECT Villan	nova University - Lancaster Avenue H	Housing PROJECT NO. 056756.277					
CLIENT Radno	or Township	DATE 03/30/2017					
Arrival Time 7:00a Departure Time 5:00p Total Hours 10 hrs	Site Condition: Clear Mud	Site Condition:					
CONTRACTOR Torcon, Inc.		SUBCONTRACTOR(S) Mayfield Site Cont. Inc, Molly Conc. Cont, Inc., D.M. Sabia, Inc.					
LABOR FORCE		WORK PERFORMED					
Superintendent 1 Foreman 1 Operators 2 Laborers 5 Drivers 6 EQUIPMENT USED Excavator 3 FEL Dump Truck 5 Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other 1	202 to manhole MH-230. Residual dump truck for export off site. The reinforced concrete pipe (RCP) at Materials were set upon 6+ inches modified stone, trench backfill was walk along vibratory roller. 2.) Mayfield continued removing background along the north side. Also, Molly western end of the east building. Lare hauling the material offsite. Trand debris being dropped offsite. At the site paved areas and surrounding 3.) Trucks delivering concrete and on the paved and stoned sections of prescribed dumpster(s).	2.) Mayfield continued removing bulk soil and materials for the foundation areas of the east building along the north side. Also, Molly Concrete contractors excavated for foundation footings in the western end of the east building. Large track-hoe excavators are loading tri-axle dump trucks which are hauling the material offsite. Trucks are processing through a tire wash station to cut down on mud and debris being dropped offsite. Additionally, Mayfield has a street sweeper subcontracted to clean the site paved areas and surrounding roads. 3.) Trucks delivering concrete and grout for Molly and D.M. Sabia (mason) were primarily remained on the paved and stoned sections of the lot, discarded portland based materials were placed in the					
	SKETCH	COMMENTS					
		1 Technician from Geostructures, Inc., and 1 from Advanced Geosystems, Inc. were onsite today. INSPECTOR: William Wood-Jenkins - Gannett Fleming					