

INSPECTOR'S DAILY REPORT

PROJECT Villand	ova University - Lancaster Avenue F	Housing	PROJECT NO. 056756.277			
CLIENT Radnor	CLIENT Radnor Township			04/06/2017		
Arrival Time 7:00a Departure Time 1:30p Total Hours 6.5 hrs	Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Wet ☐ Snow ☐ Ice ☐ Foggy Temp Range: 40°F to 50°F					
CONTRACTOR Torcon, Inc.		SUBCON	SUBCONTRACTOR(S) Mayfield Site Cont. Inc., Molly Concrete Co., Inc.			
LABOR FORCE		WORK PERFORMED				
Superintendent 1 Foreman 2 Operators 3 Laborers 6 Drivers 4 EQUIPMENT USED: Excavator 2 FEL Dump Truck 4 Backhoe Hoe Pac Vibratory Roller Motorized Tamper 1 Other 1	1.) Mayfield Site Construction (M MH-202. Residual material was exexport off site. The contractor set grade and the manhole structure set stone, also pipe was encased in 18 due to the heavy rains that were st 2.) Roadways around the site are extreet sweeper continues to make a being processed through a tire was designed with the heavy rain cond 3.) Molly Concrete Contractors, In buildings. Concrete trucks primari portland based materials were placed.	xcavated from 2 lengths (above the continued of the conti	on the area and placed out 40 ft.) of 30 inch of H-202. Materials were clean stone. No tre out the work. The clean and free of deep the site and perime as construction of the foon the paved and stone.	in a tri-axle dump truck for diameter HDPE pipe at 0.007ft/ft re set upon 6+ inches of 2B clean ench backfill was placed today bris, no build up of mud/dirt; the ster roads, and outgoing trucks are erved to be functioning as		
	SKETCH		CON	MMENTS		
		INSP	ECTOR: iam Wood-Jenkins - O			