

<b>PROJECT</b>	<u>Villanova University - WLA Parking Lot</u>	<b>PROJECT NO.</b>	<u>056756.249</u>
<b>CLIENT</b>	<u>Radnor Twsp.</u>	<b>DATE</b>	<u>12/24/2015</u>

Arrival Time	<u>7:00a</u>	Weather:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Overcast	<input checked="" type="checkbox"/> Rain	<input type="checkbox"/> Hot	<input type="checkbox"/> Warm	<input checked="" type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	<u>3:00p</u>	Site Condition:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Muddy	<input type="checkbox"/> Dusty	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	<u>8.0</u>	Temp Range:	<u>55°F to 70°F</u>						

<b>CONTRACTOR</b> <u>Torcon</u>	<b>SUBCONTRACTOR(S)</b> <u>JJD, Mayfield, HB Frazier, Federal Fence</u>
---------------------------------	---

<b>LABOR FORCE</b>	<b>WORK PERFORMED</b>
Superintendent <u>1</u>	1.) Federal Fence was onsite and completed the excavation and installation of the 6' tall wooden post for the proposed permanent site safety fence that runs along the southern property line. 2.) HB Frazier was onsite to core drill @ Moriarty Hall but it was locked up and they could not gain access. 3.) Due to the extremely muddy site conditions, there was concern that the concrete delivery truck would become stuck on site. JJD assisted Federal Fence by using their equipment onsite to ferry the concrete from the delivery truck to the locations which Federal Fence was installation the 6' tall wooden posts for the permanent safety fence.
Foreman <u>1</u>	
Operators <u>3</u>	
Laborers <u>2</u>	
Drivers <u>1</u>	
<b>EQUIPMENT USED:</b>	
Excavator <u>4</u>	
FEL _____	
Dump Truck <u>2</u>	
Backhoe <u>1</u>	
Hoe Pac _____	
Vibratory Roller <u>1</u>	
Motorized Tamper _____	
Other <u>1</u>	
Tub Grinder <u>1</u>	
Bulldozer <u>1</u>	
Skidder _____	

<b>SKETCH</b>	<b>COMMENTS</b>
	1.) Marilou (Villanova) was onsite today. 2.) Three (3) old manholes were discovered between Griffin Hall & Moriarty Hall. They appear to be old abandoned manholes. They will look into these manholes before taking any action. 3.) Heavy rain all day made the site very wet and muddy.
	<b>INSPECTOR:</b> <u>Jason Thompson - Gannett Fleming</u>

