

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Township	DATE 01/18/2017

Arrival Time <u>12:45</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>1:15</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>0.5 hrs</u>	Temp Range: <u>36°F</u> to <u>45°F</u>

CONTRACTOR Torcon	SUBCONTRACTOR(S) Molly, Mayfield Site Cont.,
--------------------------	---

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman _____ Operators _____ Laborers _____ Drivers _____	1) Onsite to check for any E&S control issues due to the rainfall the previous day. Roadways (Lancaster Avenue and Ithan Avenue) appeared to be clear and there does not appear to be any evidence of silt or debris at this time. 2) Tim (Torcon) informed MJP that the area between the right-in turning lane along Lancaster Avenue and the surface parking lot where the future PAC will be located is to be temporarily stoned/stabilized at the direction of the DCCD. This area is to have a small area of grass in the final condition, but it was not able to become established due to the time of the year. Tim also indicated that DCCD was providing guidance with a specific seed mix type to spread in the area located at the southeast corner of the garage structure. This area also was not able to be established during the growing season.
EQUIPMENT USED: Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
INSPECTOR: Matthew Prusko - Gannett Fleming	