

## **INSPECTOR'S DAILY REPORT**

p Range: 34°F to 43°F  te to review the safety fence instance from the modular block retains orise of 10' long 5" diameter tree.	DATE  02/14/2017  creast Rain Hot Warm Cool Cold ddy Dusty Wet Snow Ice Foggy  SUBCONTRACTOR(S)  J.J.Dougherty, Tristate Fence Co.  WORK PERFORMED
p Range: 34°F to 43°F  te to review the safety fence instance from the modular block retains orise of 10' long 5" diameter tree.	SUBCONTRACTOR(S)  WORK PERFORMED  Snow
te to review the safety fence ins EPTA rail line. Tristate Fence of from the modular block retains for the first safety from the modular block retains	WORK PERFORMED
EPTA rail line. Tristate Fence of from the modular block retaining or se of 10' long 5" diameter tree.	
EPTA rail line. Tristate Fence of from the modular block retaining or se of 10' long 5" diameter tree.	**************************************
actor placed concrete and erect .	installation along the southern side of the parking garage site against ce Co. for John J. Dougherty and Sons, Inc. finished auguring post aining wall eastward to the existing SEPTA fence. Posts are treated pine as per the project landscape drawing details. The ected posts in 5 locations adjacent to the SEPTA pedestrian access
H	COMMENTS