

INSPECTOR'S DAILY REPORT

| CLIENT Radnor | | | PROJECT NO. | 056756.277 |
|---|--|----------------|--|--|
| | Radnor Township | | DATE | 02/08/2017 |
| Arrival Time 6:45a Departure Time 4:15p Total Hours 7.5 hrs CONTRACTOR | Weather: | | | |
| LABOR FORCE | | WORK PERFORMED | | |
| Superintendent Foreman 1 Operators 2 Laborers 4 Drivers 6 EQUIPMENT USED: Excavator 2 FEL Dump Truck 5 Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other 1 | 1) Mayfield Site Construction (Mayfield) continued removing bulk soil and materials for the foundation area of the western most proposed building. A large track-hoe excavator is loading tri-axle dump trucks which are hauling the material offsite. 2) Mayfield continued excavating for storm sewer pipe and structures from MH-251 toward MH-250. The contractor set about 50' of reinforced concrete pipe (RCP) at 0.05% slope from MH-251. Pipe and structures were set upon about 6 inches of clean stone, and the pipe was also encased in the stone. Excavation spoils were exported from the site. Trench backfill is comprised of imported tan 2A modified stone being placed in approximately 12" thick lifts and compacted with a walk along vibratory roller. The contractor backfilled the pipe set between MH-251 toward MH-250. The contractor enclosed the work area in modular fencing at the conclusion of the day. 3) Starfire (subcontract for Mayfield) has a street sweeper continuously cleaning the lot and adjacent roadways to manage dirt and dust issues. | | | |
| SKETCH | | | COMMENTS | |
| | | Offsite pm for | e between 10 am to 11: alternate project/site value between 10 am to 11: alternate project/site value between 10 am to 11: | 30 am and from 2:00 pm to 3:00 visits. |