

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Township	DATE 01/12/2017

Arrival Time 12:00	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input checked="" type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time 12:30	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours 0.5 hrs	Temp Range: 44°F to 64°F

CONTRACTOR Torcon	SUBCONTRACTOR(S) Molly, Mayfield Site Cont., Reilly
--------------------------	---

LABOR FORCE	WORK PERFORMED
Superintendent 1	<p>1) Onsite to check for any E&S control issues due to the rainfall the previous day. Roadways (Lancaster Avenue and Ithan Avenue) appeared to be clear and there does not appear to be any evidence of silt or debris at this time. Reilly street sweeping was onsite traveling along Ithan and Lancaster Avenues with a stree sweeper.</p> <p>2) Tim and Justin (Torcon) informed MJP that a few sections of concrete sidewalk along the eastern side of Ithan Avenue near the Pike Garage entrance were being removed and replaced due to cracks from construction vehicles traveling along this area. The concrete is scheduled to be poured tomorrow morning and covered with blankets. The blankets are to be removed Saturday morning and the affected sidewalk area re-opened.</p> <p>3) Mayfield Site Contractors were onsite resurfacing the pavement area north of Pike Garage in the area of the future PAC. Justin informed MJP that this maintenance measure was taken to reduce dust concerns from the site. This area had been used as a laydown area for materials during Pike Garage phase and was already asphalt.</p>
Foreman 1	
Operators 3	
Laborers 4	
Drivers	
EQUIPMENT USED:	
Excavator	
FEL	
Dump Truck 1	
Backhoe	
Hoe Pac	
Vibratory Roller	
Motorized Tamper	
Other	
Steel Barrel Roller 2	

SKETCH	COMMENTS
INSPECTOR: Matthew Prusko - Gannett Fleming	

