

<b>PROJECT</b>	<u>Villanova University - WLA Parking Lot</u>	<b>PROJECT NO.</b>	<u>056756.249</u>
<b>CLIENT</b>	<u>Radnor Twsp.</u>	<b>DATE</b>	<u>12/09/2015</u>

Arrival Time	<u>8:00a</u>	Weather:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Overcast	<input type="checkbox"/> Rain	<input type="checkbox"/> Hot	<input type="checkbox"/> Warm	<input checked="" type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	<u>4:00p</u>	Site Condition:	<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Muddy	<input type="checkbox"/> Dusty	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	<u>8.0</u>	Temp Range:	<u>43°F to 54°F</u>						

<b>CONTRACTOR</b> <u>Torcon</u>	<b>SUBCONTRACTOR(S)</b> <u>JJD, HB Frazier, Davey Tree Green Mountain Clearing</u>
---------------------------------	--

<b>LABOR FORCE</b>	<b>WORK PERFORMED</b>	
Superintendent <u>1</u>	1) Green Mountain Clearing continued with the grubbing of trees, shrubs and vines today. 2) The arborist from Davey Tree continued with the root pruning along the proposed curblineline & proposed underground electrical locations. 3) Davey Tree had to move sections of the Tree Protection Fence in areas to allow them to proceed with the root pruning. After the root pruning was completed they returned the Tree Protection Fence. 4) HB Frazier continued with their layout of site electrical & teledata ductbanks. 5) Chip (JJD), Doug Siebert (Torcon) and myself walked the south property line that runs parallel to the existing train tracks to go over the installation of the 6' tall Safety Fence. This includes clearing and grubbing to allow for the fencing subcontractor access to prep and install the proposed fence. We discussed the use of a "Brush Hog" to clear the heavy underbrush, vines and trees smaller than 6" in diameter. 6) After our conversation I then contacted both Roger Phillips (GF) & John Hosbach (Rockwell) to go over the conversation and it was decided that they can use a "Brush Hog" to clear and grub the existing heavy underbrush, vines and trees smaller than 6" diameter along the proposed property line. Trees w/6" diameter or less to be documented and turned into Rockwell for review. Trees with a diameter greater than 6" cannot be removed. 7) Three (3) 100yd. containers full of "Wood Chippings" were hauled off site today.	
Foreman <u>1</u>		
Operators <u>2</u>		
Laborers <u>2</u>		
Drivers <u>1</u>		
<b>EQUIPMENT USED:</b>		
Excavator <u>3</u>		
FEL _____		
Dump Truck _____		
Backhoe _____		
Hoe Pac _____		
Vibratory Roller _____		
Motorized Tamper _____		
Other <u>1</u>		
Tub Grinder <u>1</u>		
Bulldozer <u>1</u>		
Skidder <u>1</u>		

<b>SKETCH</b>	<b>COMMENTS</b>
	1) No site visitors today. 2) Three (3) site photos labeled in the electronic file.
<b>INSPECTOR:</b>	
<u>Jason Thompson - Gannett Fleming</u>	

