

## **INSPECTOR'S DAILY REPORT**

PROJECT Villanova University - WLA Parking Lot			PROJECT NO. 0	056756.249			
CLIENT Radn	nor Twsp.		DATE 1	2/17/2015			
Arrival Time 8:000 Departure Time 3:300 Total Hours 7.5	Description: ☐Clear ☑Mudo  Temp Range: 43°F to 54°F	Site Condition:					
<b>CONTRACTOR</b> T	Forcon	SUBCON	TRACTOR(S) Cleari	·			
LABOR FORCE Superintendent 1		WORK PERFORMED  1) Green Mountain Clearing completed the clearing and grubbing today and will retun either					
Foreman	tomorrow or the following Monda 2) #4 Ballast were installed today of ballast will be installed as needed. 3) HB Frazier work trailer delivered 4) Green Mountain Clearing comp	tomorrow or the following Monday to remove the Tub Grinder. 2) #4 Ballast were installed today on top of the millings used for the Construction Entrance. More #4					
<b>EQUIPMENT USED:</b> a) Due to the heavy rain excavation was			ped for the day and will con	ontinue tomorrow.			
Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other Tub Grinder	property line that runs parallel to I  a) It was decided to put the silt so utilities being installed within the f	6) Doug (Torcon), Chip (JJD) and myself discussed the silt sock to be installed along the northern property line that runs parallel to Lancaster Ave.  a) It was decided to put the silt sock on the outside of the site safety fence due to grading and utilities being installed within the fenced area. b) This silt sock is not yet installed.					
SKETCH			COMMENTS				
		of the J 2) Larg 3) Fedd fence J 4) Toro contrac 5) Hea remain	t Prusko (GF) onsite today project and return the project and return the project paving roller delivered of the permanent of the permanent Site constant over their SOP's actors, subcontractors and or vy rain began @ 9:30 and der of the day.  ECTOR: Thompson - Gannett Flen	onsite today. /18/2015 to start installing e Safety Fence. and site safety plan with other site personnel. never let up for the			