

INSPECTOR'S DAILY REPORT

PROJECT	Villanova	University - WLA Parking Lot	PROJECT NO.	056756.249			
CLIENT	Radnor Tv	vsp.		DATE	01/11/2016		
Arrival Time Departure Time Total Hours	8:00a 4:00p 8.0			☐Hot ☐Warm ☐C	Ice □Foggy		
CONTRACTOR	Torcon		SUBCON		D, HB Frazier, DBA, Mayfield ardens		
LABOR FO	RCE	WORK PERFORMED					
Superintendent Foreman Operators Laborers Drivers EQUIPMENT	$ \frac{\frac{1}{3}}{\frac{3}{6}} $ $ \frac{6}{0} $ USED:	rolled it using a large roller. This the roadway that runs along the so 2.) JJD demolished and removed Ave. and replaced it with a new p 3.) HB Frazier backfilled all open and compaction were performed to	was observed buthern prope the existing yarecast storm i trenches that using a vibrate	tisting yard drain located (NE of Stone Hall) near Lancaster a storm inleet. This new inlet is labeled as I-133. These that were concrete encased late last week. Multiple lifts a vibratory roller.			
Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other Tub Grinder Bulldozer Skidder	1	4.) Mayfield Gardens continued installing trees and shrubs in the "Buffer Zone" area with Bob (Rockwell Associates) observing all means and methods including grading.					
	Sl	KETCH			MENTS		
			2.) Too is per visit.	Villanova and not Radn	back to 8:00am start time. This for Twsp. esp.) was onsite today for a site		