

## **INSPECTOR'S DAILY REPORT**

PROJECT	Villanova University - Church Walk & Bridge				PROJECT NO.	056756.272
CLIENT	Radnor Township				DATE	11/01/2016
Arrival Time Departure Time Total Hours	1:00 2:00 1	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy  Temp Range: 47°F to 61°F				
CONTRACTOR Torcon		SUBCONTRACTOR(S) Meco				
LABOR FO	ORCE	WORK PERFORMED				
Superintendent Foreman Operators Laborers Drivers	1 1 4	<ol> <li>Arrived onsite for required construction observation services and general site inspections.</li> <li>Meco construction onsite forming up and pouring the full reveal curb and sidewalk along westbound Lancaster Avenue where the depressed area of curbing once was in front of the existing church walkway.</li> </ol>				
EQUIPMENT	USED:					
Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other						
	SI	KETCH			COM	MENTS
				INSP	ECTOR:	
					don Shirey (Gannett Fle	eming)