

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage				PROJECT NO.	056756.256
CLIENT	Radnor Tw	Radnor Twsp.			DATE	03/09/2016
Arrival Time Departure Time Total Hours	7:00a 9:30a 1.5	Weather: ⊠Clear □Overcast □Rain □Hot ⊠Warm □Cool □Cold Site Condition: ⊠Clear □Muddy ⊠ Dusty □Wet □Snow □Ice □Foggy Temp Range: 79°F to 54°F				
CONTRACTOR Torcon		SUBCONTRACTOR(S) Mayfield Gardens WORK PERFORMED				ayfield Gardens
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer Lull	1 0 0 4 0	1.) Upon arrival to the site it was apparent addressed the E&S control issue. They ha yesterday (03/08/2016). The E&S control (03/07/2016), but was pushed back to Tue delay in addressing this issue was the resu that time. I explained to Doug (Torcon) th over construction and must be addressed in 2.) Mayfield Gardens has a small crew of 3.) The slope was raked then seeded and read 4.) Mayfield Gardens left the site as I was and straw mulch that was used to address sidewalk needed to be cleaned of all dirt at matter as I was informed.			of four (4) laborers onsite to address these issues. d matted using pins to secure it in place. vas doing my inspection and did not clean the sidewalk of dirt st the E&S control issue. I notified Doug (Torcon) that the rt and/or debris. The sidewalk was not cleaned in a timely f the site and noticed that the sidewalk had finally been	
	SI	L KETCH			COM	MENTS
				INSPI	D-8:00, 9:00-9:30 = 1.5 ECTOR: Thompson - Gannett F	