

<b>PROJECT</b> Villanova University - Pike Field Garage	<b>PROJECT NO.</b> 056756.256
<b>CLIENT</b> Radnor Twsp.	<b>DATE</b> 03/10/2016

Arrival Time	7:30a	Weather:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Overcast	<input type="checkbox"/> Rain	<input type="checkbox"/> Hot	<input checked="" type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	8:30a	Site Condition:	<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Muddy	<input checked="" type="checkbox"/> Dusty	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	1.0	Temp Range:	79°F to 55°F						

<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b>
--------------------------	-------------------------

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>0</u> Operators <u>0</u> Laborers <u>0</u> Drivers <u>0</u>	1.) No site work today. 2.) I walked the perimeter of the site to check for any E&S issues and there were none apparent at this time.
<b>EQUIPMENT USED:</b> Excavator <u>1</u> FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ Large Roller _____ Bulldozer _____ Lull _____	

SKETCH	COMMENTS
<b>INSPECTOR:</b> Jason Thompson - Gannett Fleming	