

PROJECT	<u>Villanova University - Pike Field Garage</u>	PROJECT NO.	<u>056756.256</u>
CLIENT	<u>Radnor Twsp.</u>	DATE	<u>03/11/2016</u>

Arrival Time	<u>7:00a</u>	Weather:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Overcast	<input type="checkbox"/> Rain	<input type="checkbox"/> Hot	<input checked="" type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	<u>3:30p</u>	Site Condition:	<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Muddy	<input checked="" type="checkbox"/> Dusty	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	<u>2.0</u>	Temp Range:	<u>63°F to 37°F</u>						

CONTRACTOR <u>Torcon</u>	SUBCONTRACTOR(S)
---------------------------------	-------------------------

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u>	1.) No site work today. 2.) I walked the perimeter of the site to check for any E&S issues and there were none apparent at this time. 3.) I took photos of the Temporary Sidewalk along the western side of Ithan Avenue to show the obstructions (orange safety cones & blue barrier post) that were along the walking path causing the pedestrian traffic to either walk out into the roadway or stepping over them. I forwarded these pictures to Torcon and they notified me that they were placed there by Villanova. Marilou (Villanova) was contacted and the obstructions were promptly removed.
Foreman <u>0</u>	
Operators <u>0</u>	
Laborers <u>0</u>	
Drivers <u>0</u>	
EQUIPMENT USED:	
Excavator <u>1</u>	
FEL _____	
Dump Truck _____	
Backhoe _____	
Hoe Pac _____	
Vibratory Roller _____	
Motorized Tamper _____	
Other _____	
Large Roller _____	
Bulldozer _____	
Lull _____	

SKETCH	COMMENTS
	1.) Steve Norcini (Radnor) was onsite for a general site visit. 2.) Site times: 7:00-8:30, 3:00-3:30 = 2.0 Hours
	INSPECTOR: <u>Jason Thompson - Gannett Fleming</u>

