

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Twsp.	DATE 03/12/2016

Arrival Time <u>8:00a</u>	Weather: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input checked="" type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>12:00p</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input checked="" type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>2.5</u>	Temp Range: <u>63°F</u> to <u>46°F</u>

CONTRACTOR Torcon	SUBCONTRACTOR(S)
--------------------------	-------------------------

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u>	1.) I walked the perimeter of the site to check for any E&S issues and there were none apparent at this time. 2.) JJD backfilled the holes that were created during the removal of the existing "Foul Ball" post along the third base line of the softball field. These holes were backfilled with onsite materials and compacted accordingly. 3.) JJD did the layout for the proposed sediment basin along the first base line of the existing softball field. 4.) No excavation was performed at this time.
Foreman <u>0</u>	
Operators <u>1</u>	
Laborers <u>1</u>	
Drivers <u>0</u>	
EQUIPMENT USED:	
Excavator <u>1</u>	
FEL _____	
Dump Truck _____	
Backhoe _____	
Hoe Pac _____	
Vibratory Roller _____	
Motorized Tamper _____	
Other _____	
Large Roller _____	
Bulldozer _____	
Lull _____	

SKETCH	COMMENTS
	1.) Site times: 8:00-9:30, 11:00-12:00 = 2.5 Hours
	INSPECTOR: Jason Thompson - Gannett Fleming