

## **INSPECTOR'S DAILY REPORT**

PROJECT	Villanova University - Pike Field Garage			PROJECT NO.	056756.256
CLIENT	Radnor Twsp.			DATE	03/14/2016
Arrival Time Departure Time Total Hours	7:00a 2:00p 4.0	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy  Temp Range: 63°F to 46°F			
CONTRACTOR Torcon		SUBCONTRACTOR(S)			
LABOR FORCE		WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers  EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer Lull	1	1.) I walked the perimeter of the sitime. 2.) Excavation began today near th. 3.) The existing chain link fence in excavation equipment to work in t. 4.) Test Pits were dug today and so. 5.) Installation began today on the base line of the existing softball fit. 6.) Silt Fence was temporarily inst but will be replaced on Tuesday M.	ne existing ch n this same ar his area. oil samples w proposed Te eld. alled in place	ain link fence located been was cut and remove there taken and sent out imporary Embankment to of the proposed 12" C	behind the existing Press Box. d to allow access for the for analysis. Sediment trap along the third omposite Filter Sock (CFS-06)
	SI	LKETCH		COMI	MENTS
			INSP	e times: 7:00-7:30, 8:30  ECTOR: Thompson - Gannett F	Fleming