

PROJECT	<u>Villanova University - Pike Field Garage</u>	PROJECT NO.	<u>056756.256</u>
CLIENT	<u>Radnor Twsp.</u>	DATE	<u>03/22/2016</u>

Arrival Time	<u>9:30a</u>	Weather:	<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Overcast	<input type="checkbox"/> Rain	<input type="checkbox"/> Hot	<input checked="" type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	<u>11:00a</u>	Site Condition:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Muddy	<input type="checkbox"/> Dusty	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	<u>1.5</u>	Temp Range:	<u>55°F to 45°F</u>						

CONTRACTOR	<u>Torcon</u>	SUBCONTRACTOR(S)	<u>JJD</u>
-------------------	---------------	-------------------------	------------

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u>	1.) Again today JJD had a two (2) man crew working onsite to excavate for the proposed Pike Field Garage. This included them hauling dirt offsite with multiple triaxle trucks. 2.) The construction entrance was maintained and it appears that all dirt and/or mud was kept in the site as designed.
Foreman <u>0</u>	
Operators <u>1</u>	
Laborers <u>1</u>	
Drivers <u>0</u>	
EQUIPMENT USED:	
Excavator <u>1</u>	
FEL _____	
Dump Truck _____	
Backhoe _____	
Hoe Pac _____	
Vibratory Roller _____	
Motorized Tamper _____	
Other _____	
Large Roller _____	
Bulldozer _____	
Lull _____	

SKETCH	COMMENTS
	1.) Site times: 7:00-8:00, 9:30-11:00 = 2.5 Hours
	INSPECTOR: <u>Jason Thompson - Gannett Fleming</u>