

<b>PROJECT</b> Villanova University - Pike Field Garage	<b>PROJECT NO.</b> 056756.256
<b>CLIENT</b> Radnor Twsp.	<b>DATE</b> 03/24/2016

Arrival Time 8:00a Weather:  Clear  Overcast  Rain  Hot  Warm  Cool  Cold  
 Departure Time 9:00a Site Condition:  Clear  Muddy  Dusty  Wet  Snow  Ice  Foggy  
 Total Hours 1.0 Temp Range: 72°F to 55°F

<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b> JJD
--------------------------	-----------------------------

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u>	1.) Again today JJD had a two (2) man crew working onsite to excavate for the proposed Pike Field Garage. This included them hauling dirt offsite with multiple triaxle trucks. 2.) The construction entrance was maintained and it appears that all dirt and/or mud was kept in the site as designed.
Foreman <u>0</u>	
Operators <u>1</u>	
Laborers <u>1</u>	
Drivers <u>0</u>	

EQUIPMENT USED:
Excavator <u>1</u>
FEL _____
Dump Truck _____
Backhoe _____
Hoe Pac _____
Vibratory Roller _____
Motorized Tamper _____
Other _____
Large Roller _____
Bulldozer _____
Lull _____

SKETCH	COMMENTS
--------	----------

	1.) Site times: 8:00-9:00 = 1.0 Hours                          
<b>INSPECTOR:</b>	
Jason Thompson - Gannett Fleming	