

INSPECTOR'S DAILY REPORT

| PROJECT | Villanova University - Pike Field Garage | | | PROJECT NO. | 056756.256 |
|--|--|--|---------------------------------|--|--|
| CLIENT | Radnor Twsp. | | | DATE | 03/29/2016 |
| Arrival Time Departure Time Total Hours | 8:30a 1:30a 2.5 | Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Wet ☐ Snow ☐ Ice ☐ Foggy Temp Range: 54°F to 30°F | | | |
| CONTRACTOR Torcon | | | | | |
| LABOR FORCE | | WORK PERFORMED | | | |
| Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer Lull | 1 1 10 1 | Again today JJD had a two (2) Garage. This included them haulir The construction entrance was site as designed. A sweeper truck was onsite all | ng dirt offsite maintained a | with multiple triaxle tr and it appears that all di | ucks. rt and/or mud was kept in the |
| | Sl | LKETCH | | COM | MENTS |
| | | | 2.) Ste with T concer during | orcon to go over the Ra | d I had a small meeting onsite adnor Township policy keeping them clean at all times |