Gannett Fleming

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage	**PROJECT NO.**	056756.256
CLIENT	Radnor Twsp.	**DATE**	03/30/2016

Arrival Time	7:30a	Weather:	☒Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☒Cool ☐Cold
Departure Time	12:30p	Site Condition:	☐Clear ☐Muddy ☐ Dusty ☒Wet ☐Snow ☐Ice ☐Foggy
Total Hours	2.0		
		Temp Range:	57°F to 43°F

CONTRACTOR Torcon

SUBCONTRACTOR(S) JJD

LABOR FORCE

Superintendent	1
Foreman	0
Operators	1
Laborers	1
Drivers	0

EQUIPMENT USED:

Excavator	1
FEL	1
Dump Truck	10
Backhoe	1
Hoe Pac	
Vibratory Roller	
Motorized Tamper	
Other	
Large Roller	
Bulldozer	
Lull	

WORK PERFORMED

1.) Again today JJD had a two (2) man crew working onsite to excavate for the proposed Pike Field Garage. This included them hauling dirt offsite with multiple triaxle trucks.
2.) The construction entrance was maintained and it appears that all dirt and/or mud was kept in the site as designed.
3.) A sweeper truck was onsite all day to help with keeping the roadways clear of dirt and debris.
4.) Excavation began at the SW corner of the lot near the temporary crosswalk along Ithan Ave. This is for the proposed caissons to be installed.
5.) The existing iron fence along the property line was demoed and fully removed to allow further excavation within this area.

SKETCH

COMMENTS

1.) Site times: 7:30-9:00, 12:00-12:30 = 2.0 Hours

INSPECTOR:
Jason Thompson - Gannett Fleming