

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Twsp.	DATE 03/31/2016

Arrival Time 7:30a Weather: Clear Overcast Rain Hot Warm Cool Cold
 Departure Time 12:30p Site Condition: Clear Muddy Dusty Wet Snow Ice Foggy
 Total Hours 2.0 Temp Range: 73°F to 61°F

CONTRACTOR Torcon	SUBCONTRACTOR(S) JJD
--------------------------	-----------------------------

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>0</u> Operators <u>1</u> Laborers <u>1</u> Drivers <u>0</u>	1.) CJ Drilling was onsite today with the drill rig and all drill accessories to begin the installation for the proposed caissons to be installed along Ithan Ave. 2.) MG tree was onsite removing all trees clearly marked for removal. 3.) SEPTA had their own tree removal company onsite to remove all trees clearly marked for removal. SEPTA only removed trees on their property.
EQUIPMENT USED:	
Excavator <u>1</u> FEL <u>1</u> Dump Truck <u>10</u> Backhoe <u>1</u> Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ Large Roller _____ Bulldozer _____ Lull _____	

SKETCH	COMMENTS
	1.) Site times: 7:30-9:00, 10:00-11:00 = 2.5 Hours
	INSPECTOR: Jason Thompson - Gannett Fleming