

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage				PROJECT NO.	056756.256
CLIENT	NT Radnor Twsp.				DATE	04/01/2016
Arrival Time Departure Time Total Hours	8:30a 1:30p 1.5	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy Temp Range: 73°F to 52°F				
CONTRACTOR Torcon		SUBCONTRACTOR(S) JJD				D
LABOR FORCE		WORK PERFORMED				
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer Lull	1 1 10 1	the proposed saisson 2.) MG tree was ons 3.) SEPTA also had removal due to SEP (Radnor) and he sai us due to them bein allowed to proceed. 4.) JJD continued to	ns to be installed site and completed to remove some PTA classifying and they are allowed they are allowed classified as the complete that they are allowed the	ed along Ithau eted the remo ne trees on the g them as "Ha wed to remov "Hazardous". te from the extended the second of the seco	n Ave. oval all trees that were cleir side of the property azardous". I relayed this te trees on their propert. I notified Torcon and	line that were not marked for s message to Steve Norcini by without any clarification from the contractor that they were used Pike Field Garage.
	S	L KETCH			COM	MENTS
				INSP	ECTOR: Thompson - Gannett F	0-1:30 = 1.5 Hours