

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Twsp.	DATE 04/01/2016

Arrival Time	8:00a	Weather:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Overcast	<input checked="" type="checkbox"/> Rain	<input type="checkbox"/> Hot	<input checked="" type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	9:00a	Site Condition:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Muddy	<input type="checkbox"/> Dusty	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	1.0	Temp Range:	67°F to 48°F						

CONTRACTOR Torcon	SUBCONTRACTOR(S) JJD
--------------------------	-----------------------------

LABOR FORCE	WORK PERFORMED																					
<table style="width:100%;"> <tr><td>Superintendent</td><td align="right">1</td></tr> <tr><td>Foreman</td><td align="right">0</td></tr> <tr><td>Operators</td><td align="right">1</td></tr> <tr><td>Laborers</td><td align="right">1</td></tr> <tr><td>Drivers</td><td align="right">0</td></tr> </table>	Superintendent	1	Foreman	0	Operators	1	Laborers	1	Drivers	0	<p>1.) No one was onsite today upon my arrival. I had not been notified of this change in the work schedule through any communication from Torcon. The contractor had previously indicated that work was scheduled for today in an email dated March 31, 2016.2.) I walked the entire site to check on all installed E&S controls which all appear functional at this time.</p>											
Superintendent	1																					
Foreman	0																					
Operators	1																					
Laborers	1																					
Drivers	0																					
EQUIPMENT USED:																						
<table style="width:100%;"> <tr><td>Excavator</td><td align="right">1</td></tr> <tr><td>FEL</td><td align="right">1</td></tr> <tr><td>Dump Truck</td><td align="right">10</td></tr> <tr><td>Backhoe</td><td align="right">1</td></tr> <tr><td>Hoe Pac</td><td align="right">_____</td></tr> <tr><td>Vibratory Roller</td><td align="right">_____</td></tr> <tr><td>Motorized Tamper</td><td align="right">_____</td></tr> <tr><td>Other</td><td align="right">_____</td></tr> <tr><td>Large Roller</td><td align="right">_____</td></tr> <tr><td>Bulldozer</td><td align="right">_____</td></tr> <tr><td>Lull</td><td align="right">_____</td></tr> </table>	Excavator	1	FEL	1	Dump Truck	10	Backhoe	1	Hoe Pac	_____	Vibratory Roller	_____	Motorized Tamper	_____	Other	_____	Large Roller	_____	Bulldozer	_____	Lull	_____
Excavator	1																					
FEL	1																					
Dump Truck	10																					
Backhoe	1																					
Hoe Pac	_____																					
Vibratory Roller	_____																					
Motorized Tamper	_____																					
Other	_____																					
Large Roller	_____																					
Bulldozer	_____																					
Lull	_____																					

SKETCH	COMMENTS
	<p>1.) Site times: 8:00-9:00 = 1.0 Hours</p>
	<p>INSPECTOR: Jason Thompson - Gannett Fleming</p>