

INSPECTOR'S DAILY REPORT

PROJECT	Villanova - Pike Field Garage			PROJECT NO.	056756.256
CLIENT	Radnor Township			DATE	04/13/2016
Arrival Time Departure Time Total Hours	10:30 12:30 2hrs	Weather:			
CONTRACTOR JJD LABOR FORCE		SUBCONTRACTOR(S) WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Bull Dozer	1 1 4 5 3 S USED:	1) Contractor is onsite excavating the footers for the proposed parking structure along side Ithan Avenue and stockpiling per spec in the area outlined within the approved erosion and sedimentation site plan. 2) Contractor is installing shoring timbers along side Ithan Avenue in the areas of footer excavation to prevent dirt and roadway from collapsing into proposed parking garage area. 3) After excavated soils were relocated to topsoil stockpile the onsite contractor spread, sloped and graded all dirt per E&S topsoil plan/spec. 4) Prior to leaving site for the day I performed an inspection of contractor installed erosion and sedimentation controls. All of the installed controls onsite are in place, intact and fully operational.			
	SI	KETCH		COM	MENTS
				covering site today for	r Jason Thompson.
				lon Shirey	