

PROJECT <u>Villanova University - Pike Field Garage</u>	PROJECT NO. <u>056756.256</u>
CLIENT <u>Radnor Twsp.</u>	DATE <u>04/20/2016</u>

Arrival Time 11:00a Weather: Clear Overcast Rain Hot Warm Cool Cold
 Departure Time 11:30a Site Condition: Clear Muddy Dusty Wet Snow Ice Foggy
 Total Hours 0.5
 Temp Range: 70°F to 43°F

CONTRACTOR <u>Torcon</u>	SUBCONTRACTOR(S) <u>JJD, Cook Drilling</u>
---------------------------------	---

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>0</u> Operators <u>1</u> Laborers <u>1</u> Drivers <u>0</u>	1.) I walked the entire site to check on all installed E&S controls which all appear functional at this time. 2.) Cook Drilling continues to drill for the proposed caissons. 3.) The required 12" Silt Sock was installed today around the entire stockpile.

EQUIPMENT USED:	
Excavator	<u>1</u>
FEL	<u>1</u>
Dump Truck	<u>10</u>
Backhoe	<u>1</u>
Hoe Pac	_____
Vibratory Roller	_____
Motorized Tamper	_____
Other	_____
Large Roller	_____
Bulldozer	_____
Lull	_____

SKETCH	COMMENTS
--------	----------

1.) Site times: 11:00-11:30 = 0.5 Hour

INSPECTOR: <u>Jason Thompson - Gannett Fleming</u>
--