Gannett Fleming

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage	**PROJECT NO.**	056756.256
CLIENT	Radnor Twsp.	**DATE**	04/21/2016

Arrival Time	11:00a	Weather:	☒Clear ☐Overcast ☐Rain ☐Hot ☒Warm ☐Cool ☐Cold
Departure Time	12:30p	Site Condition:	☒Clear ☐Muddy ☒ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy
Total Hours	1.5		
		Temp Range:	73°F to 57°F

CONTRACTOR Torcon

SUBCONTRACTOR(S) JJD, Cook Drilling

LABOR FORCE

Superintendent	1
Foreman	0
Operators	1
Laborers	1
Drivers	0

EQUIPMENT USED:

Excavator	1
FEL	1
Dump Truck	10
Backhoe	1
Hoe Pac	
Vibratory Roller	
Motorized Tamper	
Other	
Large Roller	
Bulldozer	
Lull	

WORK PERFORMED

1.) I walked the entire site to check on all installed E&S controls which all appear functional at this time.
2.) Cook Drilling continues to drill for the proposed caissons.
3.) JJD continued with excavation and removal of dirt from the site.
4.) A second Construction Entrance was installed on the Eastern side of Ithan Avenue near the existing SEPTA overpass. This was installed to allow the drilling operation to continue installing the caissons.
5.) Sweeper truck onsite all day.

SKETCH

COMMENTS

1.) Site times: 11:00-12:30 = 1.5 Hour

INSPECTOR:
Jason Thompson - Gannett Fleming