

| | |
|---|-------------------------------|
| PROJECT Villanova University - Pike Field Garage | PROJECT NO. 056756.256 |
| CLIENT Radnor Twsp. | DATE 05/02/2016 |

| | |
|------------------------------|---|
| Arrival Time <u>11:00a</u> | Weather: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input checked="" type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold |
| Departure Time <u>11:30a</u> | Site Condition: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy |
| Total Hours <u>0.5</u> | Temp Range: <u>70°F</u> to <u>52°F</u> |

| | |
|--------------------------|--|
| CONTRACTOR Torcon | SUBCONTRACTOR(S) JJD, Cook Drilling |
|--------------------------|--|

| LABOR FORCE | WORK PERFORMED |
|---|--|
| Superintendent <u>1</u> Foreman <u>0</u> Operators <u>1</u> Laborers <u>1</u> Drivers <u>0</u> | 1.) I walked the entire site to check on all installed E&S controls which all appear functional at this time. 2.) Cook Drilling continues to drill for the proposed caissons. |
| EQUIPMENT USED: Excavator <u>1</u> FEL <u>1</u> Dump Truck <u>10</u> Backhoe <u>1</u> Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ Large Roller _____ Bulldozer _____ Lull _____ | |

| SKETCH | COMMENTS |
|--------|---|
| | |
| | INSPECTOR: Jason Thompson - Gannett Fleming |