

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage			PROJECT NO.	056756.256
CLIENT	Radnor Tv	vsp.		DATE	05/05/2016
Arrival Time Departure Time Total Hours	10:30a 11:30a 1.0	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy Temp Range: 57°F to 46°F			
CONTRACTOR Torcon		SUBCONTRACTOR(S) JJD, Cook Drilling			O, Cook Drilling
LABOR FORCE		WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer Lull	1 1 10 1	1.) I walked the entire site to check time. 2.) Cook Drilling continues with d 3.) JJD installed two more loads of the SEPTA overpass. These two (2 more time to clean off the tires and	rilling and in f #4 Ballast to l) loads were	stallation for the propose to the Construction Entra added to extend the roa	sed caisson installation. ance off of Ithan Avenue near
SKETCH				COMMENTS	
				ECTOR: 1 Thompson - Gannett F	leming