Gannett Fleming

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage	**PROJECT NO.**	056756.256
CLIENT	Radnor Twsp.	**DATE**	05/10/2016

Arrival Time	9:00a	Weather:	☐Clear ☒Overcast ☒Rain ☐Hot ☐Warm ☒Cool ☐Cold
Departure Time	9:30a	Site Condition:	☐Clear ☐Muddy ☐ Dusty ☒Wet ☐Snow ☐Ice ☐Foggy
Total Hours	0.5		
		Temp Range:	55°F to 48°F

CONTRACTOR Torcon

SUBCONTRACTOR(S) JJD, Cook Drilling

LABOR FORCE

Superintendent	1
Foreman	0
Operators	1
Laborers	1
Drivers	0

EQUIPMENT USED:

Excavator	1
FEL	1
Dump Truck	10
Backhoe	1
Hoe Pac	
Vibratory Roller	
Motorized Tamper	
Other	
Large Roller	
Bulldozer	
Lull	

WORK PERFORMED

1.) I walked the entire site to check on all installed E&S controls which all appear functional at this time.
2.) Cook Drilling continues with drilling and installation for the proposed caisson.
3.) JJD installed orange barricades along the open trench area as a secondary means of site protection for the proposed caisson installation near the Construction Entrance off Ithan near Lancaster Ave.
4.) Multiple concrete trucks onsite today for the installation of the proposed caissons.

SKETCH

COMMENTS

1.) Site times: 9:00-9:30 = 0.5 Hour

INSPECTOR:
Jason Thompson - Gannett Fleming