

INSPECTOR'S DAILY REPORT

| PROJECT | Villanova - Pike Field Garage | | | PROJECT NO. | 056756.256 |
|---|-------------------------------|---|----------------|----------------------|--|
| CLIENT | Radnor Township | | | DATE | 05/13/2016 |
| Arrival Time Departure Time Total Hours | 8:00 9:00 1hrs | Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Snow ☐ Ice ☐ Foggy Temp Range: 60°F to 70°F | | | |
| CONTRACTOR JJD | | SUBCONTRACTOR(S) Cook Drilling | | | |
| LABOR FORCE | | WORK PERFORMED 1) Arrived onsite for construction observation services and general site inspections. | | | |
| Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Bull Dozer | 3 3 | 2) Cook is onsite drilling holes for 3) Prior to leaving site for the day sedimentation controls. All of the interpretation of the interpretation controls. | parking gara | age footers. | ctor installed erosion and |
| | | | | | |
| | SI | KETCH | | | MENTS |
| | | | 2) Tota report | and travel times. | r Jason Thompson. etion observation services, daily |
| | | | | ECTOR: don Shirey | |