

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Twsp.	DATE 05/16/2016

Arrival Time <u>11:30a</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input checked="" type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>12:00p</u>	Site Condition: <input type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>0.5</u>	Temp Range: <u>67°F</u> to <u>42°F</u>

CONTRACTOR Torcon	SUBCONTRACTOR(S) JJD, Cook Drilling
--------------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>0</u> Operators <u>1</u> Laborers <u>1</u> Drivers <u>0</u>	1.) I spoke with Doug (Torcon) who confirmed that the sweeper truck would be onsite all day to keep the roadway clear of debris. I witnessed the sweeper truck complete several circuits along Ithan Avenue to address the dirt accumulation on the roadway. 2.) Cook Drilling continues with drilling and installation for the proposed caissons.
EQUIPMENT USED: Excavator <u>1</u> FEL <u>1</u> Dump Truck <u>10</u> Backhoe <u>1</u> Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ Large Roller _____ Bulldozer _____ Lull _____	

SKETCH	COMMENTS
	INSPECTOR: M. Prusko - Gannett Fleming