

## **INSPECTOR'S DAILY REPORT**

PROJECT	Villanova	University - Pike Field Garage	PROJECT NO.	056756.256	
CLIENT	Radnor Twsp.			DATE	05/23/2016
Arrival Time Departure Time Total Hours	7:30a 3:00p 3.0	Site Condition: $\square$ Clear $\square$ Much Temp Range: $\underline{75}^{\circ}$ F to $\underline{54}^{\circ}$ F	ldy 🗌 Dusty	☐Hot ☑Warm ☐  / ☐Wet ☐Snow ☐	]Ice □Foggy
CONTRACTOR Torcon  LABOR FORCE				TRACTOR(S) JJD, Cook Drilling, Molly PERFORMED	
Superintendent Foreman Operators Laborers Drivers  EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other Large Roller Bulldozer Lull	1 0 1 1 0 <b>USED:</b> 1 1 10 1	1.) I walked the entire site to chectime. 2.) Cook Drilling continues with 3.) Molly Construction continues 4.) Multiple truck loads of concre 5.) JJD began with demolition of installation is set to be installed. 6.) JJD excavated at the existing Lancaster Avenue then core drilled.	drilling and in with the footo the existing profile is along I sanitary sewer	nstallation for the proper installation for the possite.  aved area where the plancaster Avenue juts manhole near the cor	osed Caisson installation. proposed parking garage. roposed sanitary sewer to the East of Ithan Avenue. astruction entrance off of
	Sl	KETCH 1) Site t		COMMENTS times: 7:30-8:00, 12:30-3:00	
			2.) DB cylinds	A onsite to check on o	compaction and to take test