

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage			PROJECT NO.	056756.256
CLIENT	Radnor Twsp.			DATE	05/25/2016
Arrival Time Departure Time Total Hours	7:30a 2:30p 3.0	Site Condition: ☐ Clear ☐ Mudo Temp Range: 88°F to 63°F	dy Dusty		
LABOR FORCE		SUBCONTRACTOR(S) JJD, Cook Drilling, Molly WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers EQUIPMEN Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamp Other Large Roller Bulldozer Lull	1 0 1 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.) I walked the entire site to check time. 2.) Cook Drilling continues with day. 3.) Molly Construction continues with day. 4.) Multiple truck loads of concrete to the continues of the continu	c on all instal rilling and in with the foote e delivered of avy rock near SDR-35 to S the dust cont	lled E&S controls who istallation for the proper installation for the positie. In the intersection of L Sta. 2+16 before backgrol.	posed Caisson installation. proposed parking garage. ancaster & Ithan. They picked up filling and compaction.
	S	KETCH		CON	MMENTS
			2.) DB cylindo		compaction and to take test