

## **INSPECTOR'S DAILY REPORT**

PROJECT	Villanova University - Pike Field Garage			PROJECT NO.	056756.256
CLIENT	Radnor Twsp.			DATE	06/06/2016
Arrival Time Departure Time Total Hours  CONTRACTO	11:00a 3:00p 2.5	Site Condition: ☐Clear ☑Mude  Temp Range: 75°F to 64°F	dy Dusty	☐Hot ☑Warm ☐ ✓ ☑Wet ☐Snow ☐	]Ice □Foggy
LABOR FORCE		SUBCONTRACTOR(S) JJD, Cook Drilling, Molly WORK PERFORMED			JD, Cook Drilling, Molly
Superintendent Foreman Operators Laborers Drivers  EQUIPMEN Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamp Other Large Roller Bulldozer Lull	1 0 1 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.) I walked the entire site to check time. 2.) JJD continued with excavation MH-S8 (Located in Ithan Ave.) us due to the heavy rock. The trench patch for a smooth transition. 3.) Molly Construction continues v. 4.) Sweeper truck onsite all day.	on all instal on Ithan Ave ing the large was steel plat	lled E&S controls white for the proposed san rock hammer attachmed and pinned with ir	itary seweer run from MH-S7 to nent. No pipe was installed today on pins then edged with cold
	S	KETCH		COM	IMENTS
			Hours 2.) DB cylinde 3.) Ma 4.) Rac vehicu VU.	A onsite to check on ders.  rilou (VU) onsite toda  dnor Police onsite help	compaction and to take test  ay.  ping with both pedestrian and  nultiple graduation ceremonies at