

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage			PROJECT NO.	056756.256
CLIENT	Radnor Twsp.			DATE	06/07/2016
Arrival Time Departure Time Total Hours	11:00a 2:30p 3.5	Site Condition: Clear Mud Temp Range: 84°F to 55°F	dy 🗌 Dusty	Hot ⊠Warm □ Wet □Snow □ TRACTOR(S) J.	
LABOR FORCE		WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers EQUIPMEN' Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamp Other Large Roller Bulldozer Lull	1 0 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.) I walked the entire site to chectime. 2.) JJD continued with excavation MH-S8 (Located in Ithan Ave.) us SDR-35 today. The trench was ste smooth transition. 3.) Molly Construction continues 4.) Sweeper truck onsite all day. 5.) Excavation for the proposed Stexisting sports field picked up again	k on all instale on Ithan Avenue ing the large el plated and with the foote ormwater Ma	lled E&S controls white for the proposed sand rock hammer attachmed pinned with iron pinser installation for the proposed sand rock hammer attachmed with iron pinser installation for the proposed sand reconstruction.	itary sewer run from MH-S7 to nent. They installed 17' of 8" then edged with cold patch for a proposed parking garage.
	Sl	KETCH		COM	IMENTS
			cylinde 2.) Rad pedesti gradua 3.) Cle	ers. dnor Police onsite aga	onsite today.