

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage				PROJECT NO.	056756.256
CLIENT	Radnor Ty	adnor Twsp.			DATE	06/08/2016
Arrival Time Departure Time Total Hours	10:30a 1:00p 2.5	Weather:				
CONTRACTOR Torcon LABOR FORCE		SUBCONTRACTOR(S) JJD, Cook Drilling, Molly WORK PERFORMED				
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer Lull	1 0 1 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	time. 2.) JJD continued MH-S8 (Located noon today due to then edged with of 3.) Molly Constr 4.) Sweeper truck 5.) JJD continued NE side of the exidue to very stron	I with excavation in Ithan Ave.) us o very strong win cold patch for a suction continues we with excavation with excavation cisting sports field gwind and rain.	on all instal on Ithan Ave ing the large d and rain. The mooth transitivith the foote for the propo-	led E&S controls which are for the proposed sanitarock hammer attachments the trench was steel plation. Ber installation for the proposed Stormwater Managain today. Excavation	ch all appear functional at this tary sewer run from MH-S7 to ent. They stopped work around ated and pinned with iron pins roposed parking garage. Agement System located at the a was stopped around noon today corner of the sports field.
	S	KETCH				MENTS
				cylinde 2.) Rac pedesti gradua	ers.	j.