

INSPECTOR'S DAILY REPORT

PROJECT Villanova University - Pike Field Garage		PROJECT NO. 056756.256	
CLIENT Radnor Twsp.		DATE 06/09/2016	
Arrival Time 8:30a Departure Time 3:00p Total Hours 4.0 CONTRACTOR Torcon	Site Condition: Clear Muddy Temp Range: 75°F to 52°F	Dusty	n
LABOR FORCE	WORK PERFORMED		
Superintendent 1 Foreman 0 Operators 1 Laborers 1 Drivers 0 EQUIPMENT USED: Excavator 1 FEL 1 Dump Truck 10 Backhoe 1 Hoe Pac Vibratory Roller Motorized Tamper Other Large Roller Bulldozer Lull	time. 2.) JJD continued with excavation or MH-S8 (Located in Ithan Ave.) using SDR-35 today. The trench was steel smooth transition. 3.) Molly Construction continues wit 4.) Sweeper truck onsite all day. 5.) JJD continued with excavation for NE side of the existing sports field p the trench with geo-fabric then install	n Ithan Ave g the large plated and th the foote or the propo- icked up a lled the sto	alled E&S controls which all appear functional at this we for the proposed sanitary sewer run from MH-S7 to e rock hammer attachment. They installed 11' of 8" d pinned with iron pins then edged with cold patch for a ster installation for the proposed parking garage. Posed Stormwater Management System located at the again today. After excavation was completed they lined sone base and leveled it off. (306) today at the NE corner of the sports field.
SI	KETCH		COMMENTS
		cylindo 2.) Rad pedesti gradua	BA onsite to check on compaction and to take test ders. adnor Police onsite again today helping with both strian and vehicular traffic due to the multiple nation ceremonies at VU. PECTOR: on Thompson - Gannett Fleming