

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage			PROJECT NO.	056756.256	
CLIENT	Radnor To	ownship		DATE	07/01/2016	
Arrival Time Departure Time Total Hours	7:00 3:00 5hrs	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy Temp Range: 64°F to 84°F				
CONTRACTOR JJD		SUBCONTRACTOR(S)				
LABOR FORCE		WORK PERFORMED				
Superintendent	1	1) Arrived onsite for required cons	struction obs	ervation services and ge	eneral site inspections.	
Foreman Operators	3	2) Molly construction onsite continuing garage wall and footer installation.				
Laborers Drivers	<u>6</u> <u>1</u>	3) Contractor is continuing electrical duct bank backfill and storm tank installation.				
EQUIPMENT		4) Contractor is moving storm inlets from staging area to their proposed install locations in preparation for work on Tuesday the 5 th .				
Excavator FEL	5) Sweeper truck onsite cleaning roadways and parking lot area of si				dirt and debris.	
Dump Truck Backhoe		6) A site wide E&S inspection discovered no problems or hazards within the installed controls. All of				
Hoe Pac		the inspected controls appear to be in place, intact and operational as per the approved plans.				
Vibratory Roller		7) Wilkinson surveying/engineering onsite marking the proposed locations of storm sewer to be				
Motorized Tampe Other	er	installed starting next week.				
Sweeper Truck	1	8) Contractor finished the storm tank installation by the end of the day and will begin stone				
backfill/geotextile fabric next week.						
	C	 KETCH		COM	MENTS	
	3.	KEICH		COM	WIEN 15	
				INSPECTOR:		
				Brandon Shirey		