

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Township	DATE 08/05/2016

Arrival Time <u>8:00</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input checked="" type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>12:00</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>2hrs</u>	Temp Range: <u>68°F</u> to <u>85°F</u>

CONTRACTOR Torcon	SUBCONTRACTOR(S) JJD, Cook Drilling, Molly
--------------------------	---

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u>	1) Arrived onsite for required construction observation services and general site inspections. 2) Mayfield Gardens is spreading topsoil and fine grading the new soccer field in the northeast area of the site. 3) JJD is excavating trench in parking lot area for duct bank installation. 4) Molly construction is using crane to continue setting precast parking garage sections into place. 5) Sweeper truck onsite all day to keep roadways and parking areas clear of dirt and debris. 6) Water truck onsite for dust control.
Foreman <u>1</u>	
Operators <u>1</u>	
Laborers <u>4</u>	
Drivers _____	
EQUIPMENT USED:	
Excavator <u>1</u>	
FEL <u>1</u>	
Dump Truck _____	
Backhoe _____	
Hoe Pac _____	
Vibratory Roller _____	
Motorized Tamper _____	
Other _____	

SKETCH	COMMENTS
	1) Left site at 9:00am and returned at 11:00am.
	INSPECTOR: Brandon Shirey - Gannett Fleming