

## **INSPECTOR'S DAILY REPORT**

PROJECT	Villanova University - Pike Field Garage			PROJECT NO.	056756.256	
CLIENT	T Radnor Township			DATE	08/10/2016	
Arrival Time Departure Time Total Hours	8:00 2:30 3.5hrs	Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Wet ☐ Snow ☐ Ice ☐ Foggy  Temp Range: 76°F to 91°F				
CONTRACTOR Torcon		SUBCONTRACTOR(S) JJD, Molly, Kehoe			D, Molly, Kehoe	
LABOR FORCE		WORK PERFORMED				
Superintendent Foreman Operators Laborers Drivers  EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Milling Machine Paving Machine	2 1 2	<ol> <li>Arrived onsite for required construction observation services and general site inspections.</li> <li>Mayfield Gardens is spreading topsoil and fine grading the new soccer field in the northeast area of the site.</li> <li>Water truck onsite for dust control.</li> <li>Sweeper truck onsite for roadway and parking lot cleanup.</li> <li>Molly construction is using crane to continue setting precast parking garage sections into place.</li> <li>JJD is setting Storm Sewer MH-240 on stone bed and backfilling with stone in 8" lifts. MH-240 was installed as shown on the approved site plans.</li> <li>Molly construction is setting more forms and pouring sidewalks along Ithan Avenue from intersection at RT. 30/Lancaster Avenue down to SEPTA tracks.</li> <li>Kehoe is milling up 3-4 feet of asphalt along the shoulder of Ithan Avenue and installing binder up to final grade temporarily until roadway is repaved.</li> </ol>				
			•			
	S	KETCH	1) I of	COMI t site at 9:30am and retu	MENTS	
			INSP	ECTOR:		
				Brandon Shirey - Gannett Fleming		