

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage			PROJECT NO. 05	56756.256	
CLIENT Radnor Township				DATE 08	8/25/2016	
Arrival Time Departure Time Total Hours	9:00 11:00 2.0 hrs			⊠Hot □Warm □Cool □Wet □Snow □Ice [Foggy	
CONTRACTOR Torcon			SUBCON	$\mathbf{TRACTOR}(\mathbf{S})$ JJD, M Reilly	Molly, High Construction,	
LABOR FORCE		WORK PERFORMED				
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other	2 1 ———————————————————————————————————	1) JJD continues with installation Installation appears to be proceedionsite for the remainder of the installation appears to be proceedionsite for the remainder of the installation. 2) Reilly had a street sweeper onsi Avenues. There was also a water tagent appears to Garage. 4) There was a two-man crew worthe west side of Ithan Avenue. The reconstructed berm.	ng as shown callation. te to control ruck onsite to work on the king on the e	on the approved plans. The dust and to continue to clea be used when dust control installation of precast section when the section of the control installation at the control of the contr	an Ithan and Lancaster I becomes an issue. ons for the Pike Parking t the SEPTA underpass on	
	Sl	KETCH		COMME	ENTS	
			INSP	ECTOR: new Prusko - Gannett Fleming		