

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage			PROJECT NO. 050	6756.256
CLIENT	Radnor To	ownship		DATE 09/	/06/2016
Arrival Time Departure Time Total Hours	10:00 2:00 2hr	Weather:			
CONTRACTOR Torcon		T			olly, Kehoe, High/Sautter
LABOR FORCE		WORK PERFORMED 1) Arrived onsite for required construction observation services and general site inspections.			
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe	$ \begin{array}{r} 1\\ \hline 1\\ 3\\ 4\\ \hline 2 \end{array} $ T USED: $ \begin{array}{r} 2\\ \hline 1\\ 2 \end{array} $	 Water truck onsite for dust control. Sweeper truck onsite for roadway and parking lot cleanup. High/Sautter is using crane to continue setting precast parking garage sections into place. JJD onsite excavating area of proposed curbing along Lancaster Ave adjacent to the Main Lot. 			
Hoe Pac Vibratory Roller Motorized Tampe Other	er				
	S	KETCH		COMMEN	
				site at 11:00am and returned	d at 1:00pm.
				don Shirey - Gannett Flemin	g