

## **INSPECTOR'S DAILY REPORT**

PROJECT	Villanova	University - Pike Field Garage		<b>PROJECT NO.</b> 0567:	56.256	
CLIENT	Radnor To	ownship		<b>DATE</b> 09/13	3/2016	
Arrival Time Departure Time Total Hours	9:00 1:00 4hrs			☐Hot ☑Warm ☐Cool ☐ ☐Wet ☐Snow ☐Ice ☐Fo		
CONTRACTOR	R Torcon		SUBCON	TRACTOR(S) JJD, Molly Roma	y, Kehoe, High/Sautter,	
LABOR FORCE		WORK PERFORMED				
Superintendent Foreman Operators Laborers Drivers  EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other	2 1 2	<ol> <li>Arrived onsite for required const</li> <li>JJD onsite excavating for Vorte structure.</li> <li>Roma concrete onsite pouring st</li> <li>Roma concrete onsite pouring st</li> <li>Roma concrete onsite pouring st</li> <li>Water truck onsite for dust const</li> <li>Sweeper truck onsite keeping romant</li> <li>High/Sautter onsite using crane</li> <li>JJD set Vortechs vault and instaplans.</li> </ol>	chs vault localection of depone proposed strol.  badways and to continue proposed strong to the continue proposed strong to continue proposed strong	ated between softball field and ressed curb at corner of Ithan A sidewalk along Lancaster Ave a parking areas clean of site dirt parking garage construction.	parking garage  Ave and Lancaster Ave.  as per the approved  and debris.	
	Sl	KETCH		COMMENT	rs	
				ECTOR:		