

INSPECTOR'S DAILY REPORT

PROJECT	Villanova	University - Pike Field Garage	PROJECT NO. 056756.256					
CLIENT	Radnor To	ownship		DATE 09/15/2016				
Arrival Time Departure Time Total Hours	10:30 2:00 3.5hrs	Weather: Clear Overcast Rain Hot Warm Cool Cold Site Condition: Clear Muddy Dusty Wet Snow Ice Foggy Temp Range: 54°F to 75°F						
CONTRACTOR Torcon			SUBCON	TRACTOR(S) SID, Monly, Renoe, High/Sautter, Roma				
LABOR FORCE		WORK PERFORMED						
Superintendent Foreman Operators Laborers Drivers	1 1 4 6 2	 Arrived onsite for required construction observation services and general site inspections. High/Sautter onsite continuing parking garage construction. Water truck onsite for dust control. Sweeper truck onsite cleaning roadways and parking areas of any site dirt and debris. 						
EQUIPMENT								
Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other	2 1 2 1 	5) Aqua onsite installing fire hydrants along Lancaster Ave in front of Main Lot. 6) JJD continuing storm sewer work in the southeast corner of the Main Lot. Contractor set MH-210 and attached riser sections to bring up to final proposed grade.						
	Sl	KETCH COMMENTS						
				PECTOR: adon Shirey - Gannett Fleming				