

<b>PROJECT</b> <u>Pike Field Garage</u>	<b>PROJECT NO.</b> <u>056756.256</u>
<b>CLIENT</b> <u>Radnor Township</u>	<b>DATE</b> <u>09/29/2016</u>

Arrival Time <u>8:30</u>	Weather: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Overcast <input checked="" type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>10:00</u>	Site Condition: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>1.5</u>	Temp Range: <u>60°F</u> to <u>65°F</u>

<b>CONTRACTOR</b> <u>Torcon</u>	<b>SUBCONTRACTOR(S)</b> <u>JJD,High</u>
---------------------------------	---

<b>LABOR FORCE</b>	<b>WORK PERFORMED</b>
Superintendent <u>1</u> Foreman <u>1</u> Operators              _____ Laborers                _____ Drivers                 _____	1) Arrived onsite for required construction observation services and general site inspections.  2) High Construction using crane to set precast parking garage sections.  3) Due to the weather there is no site work being performed today.  4) E&S controls onsite appear to be operating as intended per the approved plans.
<b>EQUIPMENT USED:</b> Excavator              _____ FEL                        _____ Dump Truck            _____ Backhoe                _____ Hoe Pac                 _____ Vibratory Roller      _____ Motorized Tamper    _____ Other                    _____ _____ _____ _____	

<b>SKETCH</b>	<b>COMMENTS</b>
	<b>INSPECTOR:</b> <u>Brandon Shirey (Gannett Fleming)</u>