

## **INSPECTOR'S DAILY REPORT**

PROJECT	Pike Field Garage			PROJECT NO.	056756.256
CLIENT	Radnor Township			DATE	10/04/2016
Arrival Time Departure Time Total Hours	9:00 3:00 4	Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Snow ☐ Ice ☐ Foggy  Temp Range: 51°F to 71°F			
CONTRACTOR Torcon		SUBCONTRACTOR(S) JJD,High,Miller Bros			
LABOR FORCE		WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers	$     \begin{array}{c}                                     $	<ol> <li>Arrived onsite for required construction observation services and general site inspections.</li> <li>High Construction using crane to set precast parking garage sections.</li> <li>Sweeper truck onsite keeping roadways and parking areas clean and clear from site dirt and debris.</li> </ol>			
EQUIPMENT	USED:	4) Millers Bros are onsite installing new masts for the traffic signals at the intersection of Ithan Avenue and Lancaster Avenue.			
Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other	1 1 2	5) JJD is laying out sidewalks along the north side of Ithan Avenue adjacent to the Field House.  6) Walked site for inspection of the installed E&S controls. All of the inspected controls appear to be in place and operational per the approved site plans.			
	SI	KETCH			MENTS
				site at 11:00am and ret	turned at 1:00pm.
				don Shirey (Gannett Fle	eming)