

INSPECTOR'S DAILY REPORT

PROJECT	Pike Field Garage			PROJECT NO.	056756.256	
CLIENT	Radnor To	ownship		DATE	10/13/2016	
Arrival Time Departure Time Total Hours	9:00 12:00 3	Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Snow ☐ Ice ☐ Foggy Temp Range: 43°F to 68°F				
CONTRACTOR Torcon		SUBCONTRACTOR(S) High,Roma				
LABOR FORCE		WORK PERFORMED 1) Arrived onsite for required construction observation services and general site inspections.				
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other	2) High Construction using crane to se sers 4 3) Sweeper truck onsite keeping roadw 4) Water truck onsite for dust control. 3) Sweeper truck onsite keeping roadw 4) Water truck onsite for dust control. 5) Roma concrete onsite pouring sidew Ave adjacent to the Main Lot. They are westbound and North Ithan Ave adjace approved plans.			lways and parking areas clean and clear from site dirt and debris.		
SKETCH				COMMENTS		
				ECTOR: don Shirey (Gannett Fle	eming)	