

INSPECTOR'S DAILY REPORT

PROJECT	Pike Field Garage			PROJECT NO.	056756.256	
CLIENT	Radnor To	Township		DATE	10/24/2016	
Arrival Time Departure Time Total Hours	7:00 2:30 4	Weather:				
CONTRACTOR Torcon			SUBCON	TRACTOR(S) Hi	gh,Aqua,CarrDuff,JJD	
LABOR FORCE		WORK PERFORMED				
Superintendent Foreman Operators	$\frac{1}{3}$	 Arrived onsite for required construction observation services and general site inspections. High Construction using crane to set precast parking garage sections. 				
Laborers Drivers	4 3	3) Sweeper truck onsite cleaning roadways and parking areas.				
EQUIPMENT USED:		4) Aqua onsite installing fire hydrants along Eastbound Lancaster Ave in front of Field House.				
Excavator 1 FEL 1		5) Carr-Duff is onsite installing new electrical wires.				
Dump Truck	3	6) Water truck onsite for dust control.				
Backhoe Hoe Pac	1	7) JJD onsite continuing excavation of new entrance off of Ithan Avenue into the Main Lot parking				
Vibratory Roller area.						
Motorized Tampe	orized Tamper 8) Walked site to inspect E&S controls. Everything appears to be in place and operational per the					
Other		approved site plans.				
		9) JJD starting to excavate for storm sewer along Ithan Avenue from inlet I-215 towards inlet I-216.				
	S]	KETCH			MENTS	
				om and returned at 1:30	arned at 10:30am. Left again at pm.	
				ECTOR: don Shirey (Gannett Fle	eming)	