

INSPECTOR'S DAILY REPORT

PROJECT	Pike Field Garage			PROJECT NO.	056756.256
CLIENT	Radnor To	Гownship		DATE	11/03/2016
Arrival Time Departure Time Total Hours	8:00 2:00 5	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy Temp Range: 46°F to 69°F			
CONTRACTOR Torcon		SUBCONTRACTOR(S) Aqua,JJD			
LABOR FORCE		WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Bull Dozer	1 1 4 1	 Arrived onsite for required construction observation services and general site inspections. Sweeper truck onsite cleaning roadways and parking areas. Aqua onsite installing fire hydrants along Eastbound Lancaster Ave in front of Field House. JJD is continuing with the stone base installation for the new entrance to the Main Lot parking area off of Ithan Avenue. JJD continuing with the storm sewer installation out of inlet I-316 toward existing MH in Lancaster Avenue. Water truck onsite for dust control. JJD installed an additional 32' of 18"RCP storm pipe out of inlet I-316. Pipe was sealed up and backfilled per the approved plans. 			
	SI	L KETCH		COM	MENTS
			INSP	ECTOR:	
			Branc	don Shirey (Gannett Fle	ming)